

**SMALL ORDER CHARGE**


Orders of \$25 or less will be subject to a \$10 small order fee.  
 Orders \$25.01 to \$50 will be subject to a \$5 small order fee.






**#85 ECLIPSE BLOW-OFF HYDRANT PARTS LIST**

PHOTO	PART NUMBER	DESCRIPTION	LIST PRICE
	X852-NEW-2024	Internally Hinged Box Complete (Design change April 2024)	\$ 322.48
851 Lid (1), 852 Box (1), 856 Clevis Pin (2), 859 Cotter Pin (2), 85WL Gear (1), 85WL-INSERT (1), COTTER PIN (1)			
	851	Internally Hinged Iron Lid (Design change April 2024)	\$ 103.93
	852	Internally Hinged Iron Box (Design change April 2024)	\$ 256.47
Due to 2024 design change, X852-NEW-2024 must be purchased to repair box or lid for units older than April 2024. No old style lids or boxes are available for repairing these units.			
	856	Clevis Pin Pin for box (requires 2 per box)	\$ 3.55
	859	Cotter Pin for box (requires 2 per box)	\$ 1.33
	X85WL	Brass Worm Lock Assembly	\$ 33.62
85WL Gear (1), 85WL-INSERT (1), COTTER PIN (1)			
	X4	Brass Top Screw Complete	\$ 145.43
4 Screw (1), 77N O-ring (1)			

	77N	O-Ring for #85 Top Screw	\$ 3.98
	X620	Brass Packing Nut with Gasket	\$ 103.54
620 Packing Nut (1), 77O Gasket (1)			
	77O	Packing Nut Gasket	\$ 5.99
	X854	Top Cap Complete	\$ 68.58
854 Top Cap (1), 857 Gasket (1), 628A-B Bolt (2), 629A-N Nut (2)			
	857	Top Cap Gasket	\$ 5.74
	X628B-B	Top Cap Bolt and Nut (requires 2 sets per cap)	\$ 3.82
628A-B Bolt (1), 629A-N Nut (1)			
	628A-B	Top Cap Bolt	\$ 2.46
	629A-N	Top Cap and Bottom Nut	\$ 1.70
	853B-N	New Style Iron Yoke	\$ 211.86
	X601A	Brass Nozzle with Gasket 2 1/2" NST	\$ 144.82
601A Nozzle (1), 669 Gasket (1)			





	669	Nozzle Gasket	\$ 7.92
	510	Brass Connecting Nut	\$ 114.42
	4FBE	Fusion Bonded Epoxy Barrel Pipe (Price per foot)	\$ 220.50
	3/4GAL	Operating Rod (price per foot) (measure exactly end to end)	\$ 24.99
	X531-NS	Plunger Complete New Style (with o-rings)	\$ 320.38
537-P Plunger (1), 539L2 Plunger Stem (1), 539W Washer (1), 2OR O-Rings (2), 541 Seat Rubber (1)			
	X566-NS	Washer Set (New Style)	\$ 67.17
541 Seat Rubber (1), 2OR O-Ring (3), 539W Washer (1)			
	541	Seat Rubber for #2	\$ 60.57
	2OR	Plunger O-Rings (Requires 2 per plunger. Older plungers may require three)	\$ 3.05
	539W	Plunger Washer	\$ 1.40
	X539L2	New Style Plunger Stem Complete	\$ 242.39
539L2 Plunger Stem (1), 2OR O-Rings (2)			
	678	Iron Coupling	\$ 90.49

	521	Brass Seat Ring	\$ 159.85
	X611	Brass Waste Tube w/ O-Ring	\$ 138.59
611 Waste Tube (1), A19 O-Ring (1)			
	A19	Waste Tube O-Ring	\$ 7.36
	A8	Bottom Gasket	\$ 8.51
	X629A	Bottom Bolt, Nut and Washer (requires 4 sets per bottom)	\$ 3.93
628A-B Bolt (1), 629A-N Nut (1), 1/2W Washer (1)			
	1/2W	1/2" Structural Bottom Washer	\$ 1.33
	X571A	Iron Bottom Complete 2" IP	\$ 689.12
571-A Bottom (1), 611 Waste Tube (1), A19 O-Ring (1), 628A-B Bolt (4), 629A-N Nut (4), 1/2W Washer, A8 Gasket (1) (NOTE: 521 Seat Ring sold separately)			
<b>#85 ECLIPSE BLOW-OFF HYDRANT OPTIONS PARTS LIST</b>			
<b>PHOTO</b>	<b>PART NUMBER</b>	<b>DESCRIPTION</b>	<b>LIST PRICE</b>
	X592D	Nozzle Cap 2 1/2" Complete	\$ 109.42
592-D Side Cap (1), A16 Gasket (3)			

	A16	Nozzle Cap Gasket (requires 3 per cap)	\$ 9.75
	4FBE-D	Domestic Fusion Bonded Epoxy Pipe (Price per foot)	\$ 275.63
	3/4GAL-D	Domestic Operating Rod (price per foot) (measure exactly end to end)	\$ 39.28
	Z85LHW	Long Handle Wrench	\$ 125.00
	85SHW	Short Handle Wrench	\$ 105.00

ADDITIONAL NOZZLE AND INLET REPAIR PARTS CAN BE FOUND ON THE  
ECLIPSE #2 POST HYDRANT PARTS PRICE LIST

### #85 ECLIPSE BLOW-OFF HYDRANT OLD STYLE PARTS LIST

PHOTO	PART NUMBER	DESCRIPTION	LIST PRICE
	X566	Washer Set (Old Style with Leathers)	\$ 76.56
541 Seat Rubber (1), 560 Cup Washer (1), 561 Cup Washer (1), 77W Washer (1)			
	X531	Plunger Complete Old Style (with leathers)	\$ 369.02
537-P Plunger (1), 541 Seat Rubber (1), 539W Washer (1), 538S Plunger Shaft (1), 538T Plunger Tip (1), 560 Cup Washer (1), 561 Cup Washer (1), 77W Washer (1), 539P2 Tip Nut (2)			
	560	Leather Cup Washer	\$ 12.27
	561	Leather Cup Washer	\$ 12.29